

FIG. 4





FIG. 5

	MONTAR	MONTAR	MONTAR
	ORBX00	ORBX0S	ORBX0 ORBX2 ORBX3 ORBX4
A	.9445	.9445	1.5745
B	3/8	1"	1"
C	.200	.200	.200
D	.750	.750	1.406
E	.094	.094	.188
F	1/16	1/16	3/32
G	3/8	3/8	3/8
H	-	1/2	1"
CAT.#	ORBX00-20	ORBX0S-20	ORBX2-20



Si usted tiene un problema específico de brochado y necesita ayuda, no dude en consultarnos.

These instructions were translated into Spanish by: