	STRAIGHT SHANKS Steel							
Straight Shanks	"H"	"E"	"P"	"0"	"A"			
-	THREAD	SHANK	THREAD	SHANK	SHOULDER	PART#		
	SIZE	DIA	LENGTH	LENGTH	DIA			
	1/4"-28	1/4"	1/4"	1-3/4"	3/8"	4		
	1/4"-28	3/8"	1/4"	1-3/4"	3/8"	E-2		
	1/4"-28	1/2"	1/4"	1-3/4"	1/2"	G-2		
	5/16"-24	1/4"	5/16"	1-3/4"	7/16"	14		
	5/16"-24	3/8"	5/16"	1-3/4"	7/16"	E-12		
← O → ← P →	5/16"-24	1/2"	5/16"	1-3/4"	1/2"	G-12		
	3/8"-24	1/4"	3/8"	1-3/4"	1/2"	24		
	3/8"-24	3/8"	3/8"	1-3/4"	1/2"	E-22		
	3/8"-24	1/2"	3/8"	1-3/4"	1/2"	G-22		
	3/8"-24	5/8"	3/8"	1-3/4"	5/8"	I-22		
	1/2"-20	3/8"	1/2"	1-3/4"	5/8"	E-32		
	1/2"-20	1/2"	1/2"	1-3/4"	5/8"	G-32		
	1/2"-20	5/8"	1/2"	1-3/4"	5/8"	I-32		
	1/2"-20	3/4"	1/2"	1-3/4"	3/4"	J-33		
	1/2"-20	1"	1/2"	2"	1"	L-33		
	5/8"-18	3/8"	5/8"	1-3/4"	3/4"	E-42		
	5/8"-18	1/2"	5/8"	1-3/4"	3/4"	G-42		
	5/8"-18	5/8"	5/8"	1-3/4"	3/4"	I-42		
	5/8"-18	3/4"	5/8"	1-3/4"	7/8"	J-43		
	5/8"-18	1"	5/8"	2"	1"	L-43		
	3/4"-16	1/2"	5/8"	1-3/4"	7/8"	G-54		
	3/4"-16	5/8"	5/8"	1-3/4"	7/8"	I-52		
	3/4"-16	3/4"	5/8"	1-3/4"	7/8"	J-53		
	3/4"-16	1"	5/8"	2"	1"	L-53		
	1"-14	1"	3/4"	2"	1-3/16"	L-63		
	1-1/4"-12	1"	3/4"	2"	1-1/2"	L-73		
	Straight Shanks with Tang							

STRAIGHT SHANKS WITH TANG Steel										
"H" THREAD SIZE	"E" SHANK DIA	"P" THREAD LENGTH	"O" SHANK LENGTH	"A" SHOULDER DIA	"U" TANG LENGTH	"T" TANG THICKNESS	PART#			
1/4"-28	1/4"	1/4"	1-3/4"	3/8"	5/16"	.122	TX-4			
1/4"-28	13/32"	1/4"	1-3/4"	13/32"	7/16"	.242	TZ-3			
5/16"-24	1/4"	5/16"	1-3/4"	7/16"	5/16"	.122	TX-14			
5/16"-24	13/32"	5/16"	1-3/4"	7/16"	7/16"	.242	TZ-13			
3/8"-24	1/4"	3/8"	1-3/4"	1/2"	5/16"	.122	TX-24			
3/8"-24	13/32"	3/8"	1-3/4"	1/2"	7/16"	.242	TZ-23			
1/2"-20	13/32"	1/2"	1-3/4"	5/8"	7/16"	.242	TZ-33			
1/2"-20	9/16"	1/2"	1-3/4"	5/8"	1/2"	.303	TH-33			
5/8"-18	13/32"	5/8"	1-3/4"	7/8"	7/16"	.242	TZ-43			
5/8"-18	9/16"	5/8"	1-3/4"	3/4"	1/2"	.303	TH-43			
3/4"-16	9/16"	5/8"	1-3/4"	7/8"	1/2"	.303	TH-53			

OMMA

È

т