



EXTERNAL ROTARY BROACHING




The process of forming an external shape on the turned O.D. of a part. This tool is used on all types of machines to produce hundreds of items. These include hex and square drivers, faucet splines, involute gears and knurled parts to name a few. Adjustable to compensate for machine misalignment.





Also available with CAT, VDI, CAPTO C6, HSK & Morse Taper Shanks



EXTERNAL ADJUSTABLE ROTATING BROACH TOOL HOLDER

Catalog Number	Α	В	С	D	E	F	G	Н	J	K
ORBX00/0.625	5/8"	1-1/2"	2-1/32"			3/8"	.300			
ORBX00/0.750	3/4"	2"	2-1/2"			1/2"	11/16"			
ORBX00/16MM	16MM			1-1/2"	2-7/16"			3/16"	24MM	1-5/8"
ORBX00/20MM	20MM	1-1/2"	2-1/32"			3/8"	.300			
ORBX00/22MM	22MM									
ORBX2/0.750	3/4"	2"								
ORBX2/1.000	1"	2	2-31/32"	2 2/0"	3-5/16"	1 /2"	.700	3/16"	40MM	2 2/0"
ORBX2/1.250	1-1/4"	3"								
ORBX2/1.500	1-1/2"									
ORBX2/20MM	20MM		2-31/32	2-3/6	3-3/10	1/2	.700	3/10	40101101	2-3/0
ORBX2/22MM	22MM	2"								
ORBX2/25MM	25MM									
ORBX2/32MM	32MM	3"								
ORBXHD/1.500	1-1/2"									
ORBXHD/1.750	1-3/4"	3"	4-3/4"	3-1/2"	4-17/32"			3/16"	2-1/2"	3-5/8"
ORBXHD/32MM	32MM									



Standard from stock H.S.S. external broaches shown on pg 19.

Note: The ORBX00/0.750 & all ORBX2/... external holders

can also be used for internal broaching!

D:#	Part Description	Part # for	Part # for	Part # for	
Diagram#	Part Description	ORBX00/	ORBX2/	ORBXHD/	
3	Spindle	ORBX00-3N	ORBX2-3N	ORBXHD-3	
16	Spindle Cap	ORBX00-16	ORBX2-16	ORBXHD-16	
17	Drive Pin	ORBX00-17	ORBX2-17	ORBXHD-17	
	Spanner Wrench	ADH00-3	ADH2-3	ORBXHD-SP	

All other features & parts are the same as the internal broach tool holders shown on top of pg. 10